

Event	Table No	Comment No	Row	ST Ref	New 1	New 2	New 3	New 4	New 5	New 6	Comment	URN	Key ref	Key Comment	Sort key
A	1	9	20	3.2	D	L				L	Ditches have been cleared (appreciated) but must be maintained	A193.2	23	Drainage /Flooding	10
A	3	1	17	3.2	D	L				L	Drainage problems need sorting out at Dove Cottage (middle of U/C Village Green).	A313.2	23	Drainage /Flooding	62
A	3	5	57	1.1	HD	F					To prevent further flooding pay particular attention to drainage requirements of new developments - parish wide	A351.1	23	Drainage /Flooding	68
B	1	18	30	3.2	F	L				L	Flooding has occurred on east side of Ickwell Green due to drainage problems. Ditches not adequately maintained, drainage problems along Sheep Walk, private owners tampering with drains, Shuttleworth opening sluice gates and affecting Ickwell. Causes need addressing.	B1183.2	23	Drainage /Flooding	127
B	1	19	31	3.2	F	L				L	Flooding also affected Hatch but local farmer diverted water flow and has built water retention constructs.	B1193.2	23	Drainage /Flooding	128
B	1	20	32	3.2	F	L				L	Golf Course in Hill Lane near Sainsbury's roundabout is conducting changes to site using landfill – will this affect the water table across the road in fields east of Upper Caldecote leading to flooding?	B1203.2	23	Drainage /Flooding	129
B	1	21	33	3.2	F	L				L	Solid paving and concrete drives with no drains to take surface water lead to flooding. Central Bedfordshire needs to reinforce the rules which say water must not be discharged onto the road	B1213.2	23	Drainage /Flooding	130
B	2	2	28	3.2	F	L				L	Flooding issues between Ickwell and Northill	B223.1	23	Drainage /Flooding	143
B	3	14	37	3.2	F						Flood prevention	B3143.2	23	Drainage /Flooding	173
B	4	14	34	3.2	F	L				L	(12) Flooding in Allan's garden (Hitchin Rd) (* Map x ref)	B4143.2	23	Drainage /Flooding	191
B	4	15	35	3.2	F	L				L	(13) Flooding in Cemetery Pound Close (* Map x ref)	B4153.2	23	Drainage /Flooding	192
B	4	16	36	3.2	F	L				L	(14) Floods between Ickwell and Northill (* Map x ref)	B4163.2	23	Drainage /Flooding	193
B	4	17	27	3.2	D	D	F	L	3		(15) Flooding on Upper Caldecote Green and Ickwell; Want all ditches/drains to be properly maintained; Caused by too many houses. More development will increase the problem (* Map x ref)	B4173.2	23	Drainage /Flooding	194
C	1	1	25	3.2	F	S	L		13	L	Water management Ickwell Road Upper C smell and flood risk	C113.2	23	Drainage /Flooding	203
C	1	14	27	3.2	D	L				L	Ditch maintenance north from Biggleswade Road. UC. Potential flood risk to south UC area	C1143.2	23	Drainage /Flooding	223
C	1	15	17	3.2	D	L				L	Pipe in ditch alongside Pound Close UC	C1153.2	23	Drainage /Flooding	224

C	1	16	28	3.2	F	L				L	Ickwell Green, Sheepwalk floods onto Ickwell Green	C1163.2	23	Drainage /Flooding	225
C	1	18	30	3.2	F	D	L		14	L	Drainage and flooding a major problem in Parish. Survey required	C1183.2	23	Drainage /Flooding	227
C	3	8	103	3.2	D	N	D	L	24	L	Improve linkage and access between Upper Caldecote and Lower Caldecote either upgrade track to byway with clear indication about access, surface maintenance and drainage upgrading taking note of bat protection.	C383.1	23	Drainage /Flooding	275
C	3	11	18	3.2	D	L				L	Flooding causes standing water for 4 or 5 months. Standing water bottom of Biggleswade Rd and Hill Lane. (UC)	C3113.2	23	Drainage /Flooding	280
C	4	10	32	3.2	F	L				L	Concerted effort by Northhill Parish Council to stop flooding at the Cemetary, which they are aware of	C4103.2	23	Drainage /Flooding	301
D	1	20		3.2	D	L				L	Flooding at Dove Cottage, also corner of Ashby Drive	D1203.2	23	Drainage /Flooding	344
D	1	21		3.2	D	L				L	Drains blocked along Hitchin rd	D1213.2	23	Drainage /Flooding	345
D	1	22		3.2	D	L				L	Need to prove drainage infrastructure could cope before building more	D1223.2	23	Drainage /Flooding	346
E	1	7	4	3.2	D	F			3		Drainage systems should be reviewed to see if they are adequate to prevent flooding	E173.2	23	Drainage /Flooding	357
E	1	7	5	3.2	F				3		Drainage systems should be reviewed to see if they are adequate to prevent flooding	E173.2	23	Drainage /Flooding	358
F	1	16		3.2	F	L				L	Ponds in LC floods around the pond and ditch area onto the fields, which then does not allow access by foot.	F1163.2	23	Drainage /Flooding	386
F	1	17		3.2	F	L				L	Caldecote Green Top end by ditch- track also gets flooded.	F1173.2	23	Drainage /Flooding	387
F	1	18		3.2	F	L				L	u/c cemetery floods	F1183.2	23	Drainage /Flooding	388
G	1	23		3.2	D	L				L	Maintain ditches in the parish particularly on the greens	G1233.2	23	Drainage /Flooding	484
G	1	24		3.2	HD	D					All new builds should not put additional pressure on already challenged sewage facilities	G1243.2	23	Drainage /Flooding	485
G	2	19		3.2	F	L					Flooding Dove Cottage, UC and UC Green	G2193.2	23	Drainage /Flooding	504
G	3	37		3.2	F						Water Lane and the UC Green flood + UC cemetery and corner of Ashby Drive	G2373.2	23	Drainage /Flooding	546
G	3	38		3.2	D						Important to keep culverts and drains free running	G2383.2	23	Drainage /Flooding	547
J	1	32		3.2	F						Field opposite G&M on west side of Hitchin Rd floods	J1323.2	23	Drainage /Flooding	592
J	2	50		3.2	D						Improve quality of maintenance and coverage of drainage facilities particularly ditches draining villages	J2503.2	23	Drainage /Flooding	614

J	2			3.2	F					Investigate and plan resolution of flooding problems and sewage issues throughout the Parish, especially in order to accommodate increased flow from further housing development.	J2513.2	23	Drainage /Flooding	615	
J	2	51		3.2	F					Issues, flooding Warden Rd Ickwell, Ickwell/Northhill near pumping station	J2543.2	23	Drainage /Flooding	618	
A	2	8	21	3.2	D	L			L	Surface Water : Cemetery; Water lane; Hill Lane corner; behind Sainsburys Petrol Station, road maintenance build culverts, re piping	A283.2	24	Drainage /Flooding	42	
A	3	1	18	3.2	D	L			L	Drainage problems behind new build Biggleswade Rd,U/C	A313.2	24	Drainage /Flooding	63	
A	3	1	19	3.2	D	L			L	Drainage problems on Methodist Church side of Ashby Drive as it meets Biggleswade Rd, U/C	A313.2	24	Drainage /Flooding	64	
A	3	4	16	3.2	D	L			L	U/C Maintain and clear out all gulleys which carry surface water more frequently than at present.	A343.2	24	Surface water flooding	67	
C	1	9	16	3.2	D	L			L	Surface water drainage flooding Warden Road Ickwell.	C193.2	24	Drainage /Flooding	216	
C	1	12	26	3.2	F	L			L	Surface water flooding opposite GM Growers UC	C1123.2	24	Drainage /Flooding	220	
J	2	52		3.2	F					Issues, surface water flooding West of Hitchin Rd UC.	J2523.2	24	Drainage /Flooding	616	
C	1	10	55	3.2	FW	D	L		17	L	Foul water drainage problem Biggleswade Rd east UC near new housing. Flooding.	C1103.2	25	Drainage /Flooding	217
C	1	11	22	3.2	D	L			18	L	Foul water drainage problem (smell) Ickwell Rd UC	C1113.2	25	Drainage /Flooding	218
C	1	11	56	3.2	S	D	L		18	L	Foul water drainage problem (smell) Ickwell Rd UC	C1113.2	25	Drainage /Flooding	219
C	1	13	23	3.2	D	L			19	L	Foul water drainage flooding Northhill Road, Ickwell.	C1133.2	25	Drainage /Flooding	221
C	1	13	57	3.2	FW	D	L		19	L	Foul water drainage flooding Northhill Road, Ickwell.	C1133.2	25	Drainage /Flooding	222
A	1	8	83	3.2	S	L				L	Sewerage issues a concern- smells at Caldecote Crossroads and B'wade Rd	A183.2	26	Drainage /Flooding	9
A	3	2	81	3.2	S	L				L	U/C Pumping station across A1 (Tingey's Corner) breaks down in prolonged wet weather – needs replacing or upgrading	A323.2	26	Sewage smells	65
A	3	3	82	3.2	S	L				L	U/C Smells outside Oaklands on Ickwell Rd, Caldecote - sewerage	A333.2	26	Drainage /Flooding	66
C	3	12	124	3.2	S	L				L	Sewage smell. (UC near cross-roads and opp Woodlands N B'wade rd UC)	C3123.2	26	Drainage /Flooding	281
C	3	13	19	3.2	D				2		General overview of water disposal and sewage disposal within the parish.	C3133.2	26	Drainage /Flooding	282

J	2	53		3.2	S					Issues, smell Ickwell Rd and Biggleswade Rd UC	J2533.2	26	Drainage /Flooding	617
J	2	55		3.2	S					Issues, foul sewage problems in region of Swallow Fields UC and A1 exit entrance Biggleswade Rd UC	J2553.2	26	Drainage /Flooding	619